

9C00	C310FC	jp FC1C
9C03	C381FC	jp FC91
9C06	C398FC	jp FC98
9C09	C3A1FC	jp FCA1
9C0C	C3BEFC	jp FCBE
9C0F	C3C9FC	jp FCC9
9C12	C3CDFC	jp FCCD
9C15	C364FD	jp FDB4
9C18	ED5B02FC	ld de, (FC02)
9C1C	2157FC	ld hl, FC57
9C1F	7E	ld a, (hl)
9C20	23	inc hl
9C21	46	ld b, (hl)
9C22	05	dec b
9C23	04	inc b
9C24	2806	jr z, 9C2C
9C26	23	inc hl
9C27	CD52FC	call FC52
9C2A	18F3	jr 9C1F
9C2C	23	inc hl
9C2D	22F4FD	ld (FDF4), hl
9C30	0E12	ld c, 12
9C32	2AF4FD	ld hl, (FDF4)
9C35	7E	ld a, (hl)
9C36	23	inc hl
9C37	46	ld b, (hl)
9C38	05	dec b
9C39	04	inc b
9C3A	2806	jr z, 9C42
9C3C	23	inc hl
9C3D	CD52FC	call FC52
9C40	18F3	jr 9C35
9C42	23	inc hl
9C43	0D	dec c
9C44	20EC	jr nz, 9C32
9C46	3E4E	ld a, 4E
9C48	0600	ld b, 00
9C4A	CD52FC	call FC52
9C4D	C9	ret
9C4E	12	ld (de), a
9C4F	13	inc de
9C50	10FC	djnz 9C4E
9C52	C9	ret
9C53	4E	ld c, (hl)
9C54	2800	jr z, 9C56
9C56	0C	inc c
9C57	F603	or 03
9C59	FC014E	call #, 4E01
9C5C	19	add hl, de
9C5D	00	nop
9C5E	00	nop
9C5F	00	nop
9C60	0C	inc c
9C61	F5	push af
9C62	03	inc bc
9C63	FE01	cp 01
9C65	00	nop
9C66	03	inc bc
9C67	0101F7	ld bc, F701
9C6A	014E16	ld bc, 164E
9C6D	00	nop
9C6E	0C	inc c
9C6F	F5	push af
9C70	03	inc bc
9C71	FB	ei
9C72	01ESFA	ld bc, FAE5
9C75	E5	push hl
9C76	06F7	ld b, F7
9C78	014E12	ld bc, 124E
9C7B	00	nop
9C7C	00	nop
9C7D	CDCEFD	call FDCE
9C80	21F6FD	ld hl, FDF6
9C83	2202FC	ld (FC02), hl
9C86	21A000	ld hl, 00A0
9C89	010001	ld bc, 0100
9C8C	CDFF1FC	call FCF1
9C8F	D20007	jp nc, 0700
9C92	CF	rst 08
9C93	2F	cpl
9C94	CDCEFD	call FDCE
9C97	CD78FD	call FD78
9C9A	C30007	jp 0700
9C9D	CDCEFD	call FDCE
9CA0	21C6FD	ld hl, FDC6
9CA3	ED5B02FC	ld de, (FC02)
9CA7	DD7E07	ld a, (ix+07)

9CAA	E604	and 04
9CAC	F6F0	or F0
9CAE	F3	di
9CAF	CD8DFD	call FD8D
9CB2	FB	ei
9CB3	E644	and 44
9CB5	CA0007	jp z,0700
9CB8	CF	rst 08
9CB9	2D	dec l
9CBA	CDCEFD	call FDCE
9CBD	0E50	ld c,50
9CBF	CD7AFD	call FD7A
9CC2	C30007	jp 0700
9CC5	2E60	ld l,60
9CC7	1802	jr 9CC8
9CC9	2E90	ld l,90
9CCB	E5	push hl
9CCC	CDCEFD	call FDCE
9CCF	E1	pop hl
9CD0	3A01FC	ld a,(FC01)
9CD3	67	ld h,a
9CD4	01FFFF	ld bc,FFFF
9CD7	CDFFFC	call FCF1
9CDA	3A0238	ld a,(3802)
9CDD	2F	cpl
9CDE	DD9601	sub (ix+01)
9CE1	DD9603	sub (ix+03)
9CE4	2078	jr nz,9D5E
9CE6	ED5302FC	ld (FC02),de
9CEA	C30007	jp 0700
9CED	C5	push bc
9CEE	E5	push hl
9CEF	210030	ld hl,3000
9CF2	3A0030	ld a,(3000)
9CF5	E6D0	and D0
9CF7	47	ld b,a
9CF8	DD7E02	ld a,(ix+02)
9CFB	E62F	and 2F
9CFD	B0	or b
9CFE	BE	cp (hl)
9CFF	2811	jr z,9D12
9D01	77	ld (hl),a
9D02	DD7E08	ld a,(ix+08)
9D05	3C	inc a
9D06	2807	jr z,9D0F
9D08	3D	dec a
9D09	2F	cpl
9D0A	320138	ld (3801),a
9D0D	1803	jr 9D12
9D0F	CD78FD	call FD78
9D12	E1	pop hl
9D13	DD4606	ld b,(ix+06)
9D16	0E14	ld c,14
9D18	7C	ld a,h
9D19	2F	cpl
9D1A	320338	ld (3803),a
9D1D	CD7AFD	call FD7A
9D20	E618	and 18
9D22	280A	jr z,9D2E
9D24	C5	push bc
9D25	CD78FD	call FD78
9D28	C1	pop bc
9D29	10ED	djnz 9D18
9D2B	CF	rst 08
9D2C	2F	cpl
9D2D	C4C1DD	call nz,DDC1
9D30	66	ld h,(hl)
9D31	06DD	ld b,DD
9D33	7E	ld a,(hl)
9D34	07	rlca
9D35	E604	and 04
9D37	B5	or l
9D38	C5	push bc
9D39	ED5B02FC	ld de,(FC02)
9D3D	E5	push hl
9D3E	21B7FD	ld hl,FDB7
9D41	CB6F	bit 5,a
9D43	2802	jr z,9D47
9D45	2EC6	ld l,C6
9D47	F3	di
9D48	CD8DFD	call FD8D
9D4B	FB	ei
9D4C	E1	pop hl
9D4D	C1	pop bc
9D4E	E67C	and 7C
9D50	C8	ret z
9D51	E66C	and 6C
9D53	37	scf
9D54	C8	ret z
9D55	E640	and 40
9D57	2802	jr z,9D5B

9D59	CF	rst 08
9D5A	2D	dec l
9D5B	25	dec h
9D5C	20D4	jr nz, 9D32
9D5E	CF	rst 08
9D5F	2F	cpl
9D60	CDCEFD	call FDCE
9D63	DD7E02	ld a, (ix+02)
9D66	E610	and 10
9D68	3200FC	ld (FC00), a
9D6B	DD7E00	ld a, (ix+00)
9D6E	3201FC	ld (FC01), a
9D71	C30007	jp 0700
9D74	0E00	ld c, 00
9D76	DD7E07	ld a, (ix+07)
9D79	E60B	and 0B
9D7B	B1	or c
9D7C	CD8DFD	call FD8D
9D7F	F5	push af
9D80	3A0138	ld a, (3801)
9D83	2F	cpl
9D84	DD7708	ld (ix+08), a
9D87	F1	pop af
9D88	C9	ret
9D89	2F	cpl
9D8A	320038	ld (3800), a
9D8D	AF	xor a
9D8E	3D	dec a
9D8F	20FD	jr nz, 9D8E
9D91	CD81FD	call FDA1
9D94	3A0038	ld a, (3800)
9D97	2F	cpl
9D98	CB47	bit 0, a
9D9A	20F5	jr nz, 9D91
9D9C	C9	ret
9D9D	3EFE	ld a, FE
9D9F	DBFE	in a, (FE)
9DA1	0F	rrca
9DA2	D8	ret c
9DA3	3E7F	ld a, 7F
9DA5	DBFE	in a, (FE)
9DA7	0F	rrca
9DA8	D8	ret c
9DA9	3E2F	ld a, 2F
9DAB	320038	ld (3800), a
9DAE	F6	ei
9DAF	76	halt
9DB0	D7	rst 10
9DB1	52	ld d, d
9DB2	05	dec b
9DB3	08	ex af, af
9DB4	78	ld a, b
9DB5	B1	or c
9DB6	3A0338	ld a, (3803)
9DB9	2804	jr z, 9DBF
9DBB	2F	cpl
9DBC	12	ld (de), a
9DBD	13	inc de
9DBE	0B	dec bc
9DBF	08	ex af, af
9DC0	ED45	retn
9DC2	08	ex af, af
9DC3	1A	ld a, (de)
9DC4	2F	cpl
9DC5	320338	ld (3803), a
9DC8	18F3	jr 9DBD
9DCA	CD0817	call 1708
9DCD	3A00FC	ld a, (FC00)
9DD0	E60F	and 0F
9DD2	06FF	ld b, FF
9DD4	F7	rst 30
9DD5	0EE5	ld c, E5
9DD7	DDE1	pop ix
9DD9	DD7E02	ld a, (ix+02)
9DDC	E60F	and 0F
9DDE	57	ld d, a
9DDF	3A00FC	ld a, (FC00)
9DE2	E610	and 10
9DE4	B2	or d
9DE5	320030	ld (3800), a
9DE8	DD7E03	ld a, (ix+03)
9DEB	2F	cpl
9DEC	320238	ld (3802), a
9DEF	C9	ret
9DF0	00	nop
9DF1	00	nop
9DF2	0D	dec c
9DF3	0A	ld a, (bc)